



Testing. Advising. Assuring.

EWFA CERTIFICATE OF ASSESSMENT	CERTIFICATE No: SFC 46234000.1	Page 1 of 1
---------------------------------------	---------------------------------------	--------------------

Report Sponsor	Certificate Issue Date	Product Name	
Velux Australia Pty Ltd 78 Henderson Road Alexandria, NSW, 2015	27/11/2017	Velux Skylights VCM 2004D and VCS 2004D	
Assessment Report Reference	Referenced Standard	Report Issue Date	Report Validity Date
EWFA 46234000.1	AS 1530.8.1- 2007	31/03/2017	31/03/2022

Introduction

The element of construction described below was assessed by this laboratory on behalf of the report sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced test report(s) or Regulatory Information Reports for a complete description of the assessed construction.

Assessed of Velux Skylights description and performance

Framed wall Description	BAL
<p>The scope of the assessment includes the bushfire resistance performance of Velux Skylights when tested in accordance with AS1530.8.1-2007 section 18 as appropriate for skylights and roof windows. The assessed skylights shall consist of;</p> <ul style="list-style-type: none"> • Velux Skylight VCM 2004D incorporating a manually operable system, i.e. without the fitment of an internal electric motor; • Velux Skylight VCS 2004D incorporating an electrically operable system and an externally mounted solar panel at the base edge for power supply to the electric motor; and • Installation of the skylights may be on a flat roof or pitched roofs of up to 75 degrees to the horizontal. <p>Refer to the referenced assessment report No. EWFA 46234000.1 for a complete description of the assessed construction and Tests EWFA 31154800 & 2686100 on similarly constructed Velux Skylights previously tested and referenced in the report.</p>	BAL A-40

Conditions/Validity

- THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE.
- Reference should be made to the relevant test report or regulatory information report to determine the applicability of the test result to a proposed installation. Full details of the constructions and justification for the conclusions given, along with the validity statements, are given in the assessment reports.
- The assessment report or short form assessment report does not provide an endorsement by Exova Warringtonfire Aus Pty Ltd of the performance of the actual products supplied. It is intended to provide a brief outline of the above referenced assessment reports and not to replace them.
- The conclusions in this certificate of assessment relate to the configurations as detailed, and should not be applied to any other configuration. The conclusions expressed in this document assess fire hazard, but it should be recognised that a single test method will not provide a full assessment of fire hazard under all conditions.
- Full copies of the assessment and relevant test reports may be obtained from the sponsor.

TESTING AUTHORITY	Exova Warringtonfire Aus Pty Ltd	
Address	Unit 2, 409-411 Hammond Road, Dandenong Victoria 3175, Australia	
Phone / Fax	+61 (0)3 9767 1000 / +61 (0)3 9767 1001	
ABN	81 050 241 524	
Email / Home Page	www.exova.com	
Authorisation	Prepared By:	Reviewed By:
	 H. Wong	 O. Saad